


Centreurs 120°
Center drills 120°
Zentrierbohrer 120°

1120



Ød1 ^T	l1	ØDh6	L	Rev. TiALN
0.50	2.00	2	39	
1.00	3.00	2	39	☑
1.10	3.00	2	39	☑
1.20	3.00	2	39	☑
1.30	3.00	2	39	☑
1.40	3.00	2	39	☑
1.50	3.00	2	39	☑
1.60	3.00	2	39	☑
1.70	3.00	2	39	☑
1.80	3.00	2	39	☑
1.90	3.00	2	39	☑
2.00	8.00	2	39	☑
2.10	8.00	2.5	39	☑
2.20	8.00	2.5	39	☑
2.30	8.00	2.5	39	☑
2.40	8.00	2.5	39	☑
2.50	8.00	2.5	39	☑
3.00	10.0	3	39	☑
4.00	12.0	4	50	☑
5.00	15.0	5	50	☑
6.00	16.0	6	60	☑



^TTol: Ød1 +0.005/ -0.01

